S-360 St. James Church Hall Oriole vicinity private c. 1880-1900

The St. James Church Hall helps define this important rural intersection along with the late nineteenth-century church and graveyard. The church hall is a two-story, gable front rectangular structure supported by brick piers and covered by narrow weatherboards. The first floor room is finished with beaded board wainscoting and plaster walls. An enclosed stair is fixed against the north wall behind the meeting room.

Survey No. S-360

Maryland Historical Trust State Historic Sites Inventory Form

Magi No. 2003605610

DOE __yes __no

			-		
1. Nam	e (indicate pr	eferred name)			
historic					
and/or common	St. James Church	h Wall			
	ation	пап			
street & number	North aids of M	D 627 Ominin Book			
		D 627, Oriole Road		not for publication	
clty, town Orio	ole	_x vicinity of	congressional district	First	
state Maryla		county	Somerset		
3. Clas	sification				
Category district building(s) structure site object	Ownership public brivate both Public Acquisition in process being consideredx not applicable	Status occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:	
4. Own	er of Prope	rty (give names a	nd mailing addresse	es of <u>all</u> owners)	
name True	stees of St. James N	4 E Church			
street & number	stees of ot. James	GIGTEN	telephone n	0.:	
city, town Oriole state			and zip code Maryland		
	ation of Lega			and	
——————————————————————————————————————	stry of deeds, etc. Clerk	· · · · · · · · · · · · · · · · · · ·		liber	
	Somerset County Co			folio	
	incess Anne	, ar enouge		MD 21853	
	resentation	in Existing	Historical Surv		
<u></u>		III Existing	AIGCOITCAT DATV	Cys	
title					
date			federal sta	te county loca	
depository for su	rvey records				
city, town			state		

7. Description

Survey No.

S-360

Condition — excellent — good — ruins — unexposed Check one — tair Check one — the check one — the check one — the check one — x original site — moved date of move — moved date of move — tair Check one — x original site — moved date of move	good	ruins		•	ve
---	------	-------	--	---	----

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

St. James Church Hall description

The St. James Church Hall stands on the north side of Oriole Road (MD627) at the intersection of Champ Road near Oriole, Somerset County, Maryland. The two-story, two-bay frame building faces south with the principal gable oriented on a north/south axis.

Built during the last quarter of the nineteenth century, this two-story, two-bay church hall is supported by a brick pier foundation and is sheathed with a uniform layer of weatherboards. The steeply pitched gable front roof is covered by a layer of asphalt shingles.

The south (main) elevation is a balanced two-bay facade with a double door entrance flanked by a pair of two-over-otwo sash windows. The second floor is lighted by identical two-over-two sash, and the east window retains a shingle louvered shutter. The eaves of the roof extend beyond the front wall surface and short returns finish the base of the roof.

The east and west sides of the building are marked by a pair of two-over-two sash windows that light each floor. A reat entrance is located in the northeast corner of the structure which provides access to the enclosed stair. An interior end brick stove stack protrudes through the roof.

The first floor interior is finished with beaded board wainscoting and plaster walls.

1400	D-1499 archeology-historic D-1599 agriculture D-1699 x architecture D-1799 art D-1899 commerce	community planning la la conservation la economics li education number n	iterature sculpture nilitary social/ nusic humanitarian
Specific	: dates	Builder/Architect	
check:	Applicable Criteria:A and/or Applicable Exception: Level of Significance:	A _B _C _D _E	
Prepare support		of significance and a gen	eral statement of history and

SIGNIFICANCE

The St. James Church Hall helps define this important rural intersection along with the late nineteenth-century church and graveyard. Since both the church and the hall have been abandoned, each structure is beginning to seriously deteriorate. The church hall appears to date from the 1880s or 1890s during the same period the church was erected.

9. Major Bibliographical References

Acreage of nominated property Quadrangle name Monie UTM References do NOT complete UTM references A Jone Easting Northing Zone Easting Northing	4000
Zone Easting Northing Zone Easting Northing	
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Verbal boundary description and justification	
List all states and counties for properties overlapping state or county boundaries	
state code county code	
state code county code	
11. Form Prepared By	
name/title Paul Touart - Archtectural Historian	
name/title Paul Touart - Archtectural Historian	
organization Somerset Co. Historical Trust date 6/2/86	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

